


POWER



MPG



FN1

FN2

FN3

FN4

Online
Error

AUTOMATION
Artisans
INC.

ELS

START

STOP

ALT

7

8

9

^
-

SCREW

TURN

Zero
Z

4

5

6

v

BEGIN

END

Zero
X

1

2

3

ESC

<<

>>

^

Z

X

·

0

DEL

OK

<

>

v